Work Order ID | 63742 Page 1 Friday, November 12, 2010 8:29:52 AM Item ID: D3951-041 Accept Setup Start **Revision ID:** Stop Item Name: Equipment Bag Assembly Start Qty: 4.00 **Start Date:** 11/12/2010 **Cust Item ID: Reg'd Oty:** 4.00 **Required Date:** 11/19/2010 **Customer:** Reference: Start Run Date: 101/- 1 Tooling: Approvals: Process Plan: Date: Stop QC: Date: **SPC (Y/N):** Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Accept Reject Reject Insp. Work Center ID Description Qty **Run Hours** Code **Qty** Number Stamp **Draw Nbr** Revision Nbr 100 0.00 0.00 Memo Small Fab 1- Assemble as per dwg 110 QC5- Inspect part completeness to step on W/O 1/W/C Memo Quality Control Identify as per dwg & Stock Location: 460 120 (e1)11/12 (4) 0.00 Packaging 0.00 Memo Packaging

D	art	: A	ere	os	pa	ce	Ltd

W/O:			WC	RK ORDER CHANGE	S							
DATE	STEP	PRO	Ву	Date Q	ty Approval Chief Eng / Prod Mgr	Approval QC Inspector						
							1100 Mgi					
								:				
	<u> </u>											
Part No						CR: Yes No DQA: Date:						
·····	Re	·			·	A: N/C Closed: Date:						
NCR:			***	ER NON-CONFORMA	NCE (NCF	K) 						
DATE	STEP	Description of NC	Initial	Corrective Action Section Action Description	n B Sign 8	Verification		Approval				
		Section A	Chief Eng	Chief Eng	Date	Section C	Chief Eng	QC Inspector				
								-				
				· · · · · · · · · · · · · · · · · · ·								
						·						

Work Order ID 63742 Friday, November 12, 2010, 8:29:52 AM Item ID: D3951-041 Accept Setup Start Revision In: Stop Equipment Bag Assembly Item Name: Start Otv: 4.00 **Start Date:** 11/12/2010 **Cust Item ID: Required Date:** 11/19/2010 Req'd Qty: 4.00 **Customer:** Reference: Run Start Process Plan: Approvals: Date: Tooling: Date: Stop QC: Date: SPC (Y/N): Date: Sequence ID/ Operation Tool ID Set Up/ Tool # Plan Reject Reject Accept Work Center ID Description

OC21- Final Inspection - Work Order Release

Memo

130

Quality Control

**Run Hours** 

0.00

0.00

10-11-17 10-11-17

Insp.

Stamp

Number

Otv

Code

Qty

Page 2

Dart	<b>Aeros</b>	pace	Ltd
------	--------------	------	-----

W/O:			W	ORK ORDER CHAN	GES						
DATE	STEP	PRO	PROCEDURE CHANGE					Approval QC Inspector			
-											
						·					
Part No		PAR #:	Fault Cate	egory:	NCR: Yes No DQA: Date:						
	•	esolution:									
NCR:			WORK ORE	ER NON-CONFORM	IANCE (NCR	)					
DATE	STEP	Description of NC	11.11		ction B	Verification		Approval			
		Section A	Initial Chief Eng	Action Description Chief Eng	Date	Section C	Chief Eng	QC Inspector			
								1			
	·										
•	1										

## **Picklist Print**

Friday, November 12, 2010 8:29:56 AM

Work Order ID: 63742

Parent Item:

D3951-041

Parent Ite... Name: Equipment Bag Asserr ly



Start Date: 11/12/2010

Start Qty: 4.00

**Required Date:** 11/19/2010


Required Qty: 4.00

_					
Co	m	m	ei	ni	ts

Comments:													
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
CBL-1240 Land IIII IIII IIII IIII IIII IIII IIII I		Purchased	No			100	Each	329.0860	,	45		/16	
				Location	<u>1</u>	Loc	<u>Oty</u>	Loc Code			,		
				ST275		329.086	0107						
		• •• .			113565	329.08	6011			4	- -		
CBL-460 		Purchased	¯ No			100	Each	94.0000	2	8	10/1	1/16.	•
				Location	1	Loc	<u>Oty</u>	Loc Code	4		/		
				ST284			66		_		_		
					114622		5		_		_		
					115579		61			<u> </u>	-		
				ST285	112002		28				_		
03949-043		Manuscratus	No		113002	100	28 East	22.0000			_	/	
Gross Weight Towing Cable F	lag Assembly	Manufactured	NO			100	Each	32.0000		PS/10	///	16.	
				Location	<u>1</u>	Loc	Oty	Loc Code		,	/ /		
				ST487			32						
					48282		32			4	_		
D3951-1 		Manufactured	No			100	Each	29.0000		4	10/11	/16	
				Location	<u>1</u>	Loc	<u>Qty</u>	Loc Code	. /		/		
				ST460	=		29			,			
					48284		29		_	4	-		

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	PROCEDURE CHANGE					Approval Chief Eng / Prod Mgr	Approval QC Inspector				
				***************************************									
-													
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes No DQA: Date:								
	R	esolution:	Dispositio	n:	QA: N/C C								
NCR:				ER NON-CONFORM				<del></del>					
DATE	OTED	Description of NC		Corrective Action Sec	ction B	Verifica			Approval QC Inspector				
DATE	STEP	Section A	Initial Action Descr Chief Eng Chief Eng		Sign Date	🖔   Section		Approval Chief Eng					
						,		;					
							•						
						,							
	•				,								



## **Dart Aerospace Ltd**

W/O:			WO	RK ORDER CHAN	IGES					
DATE	STEP	PRO	PROCEDURE CHANGE						Approval Chief Eng / Prod Mgr	Approval QC Inspector
					F44 (5) (1)					
Part No:		PAR #:	PAR #: Fault Category: N							
Resolution:			Disposition	QA	: N/C CI	osed:		Date: _`		
NCR:			WORK ORDER NON-CONFORMANCE (NCR)							
DATE	CTED	Description of NC	Corrective Action Section				Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Descriptio	n 	Sign 8 Date		on C	Chief Eng	QC Inspector
										:
									i	
		}								
				<u> </u>	-··					